



*Cadillac*

**For updates, contact your local GM Dealer.**

**For service replacement: GM p/n xxxxxxxx.**

Unauthorized copying, hiring, reproduction, storage in a retrieval system or transmission in any form or by any means, electronic, mechanical, or otherwise, is prohibited.

©2007 NAVTEQ. All rights reserved.

This data includes information taken with permission from Canadian authorities, including: ©Her Majesty the Queen in Right of Canada, ©Queen's Printer for Ontario.

Portions ©1983-2008 Microsoft Corporation. All rights reserved.

©2008 ALPINE ELECTRONICS, INC. All rights reserved.

**Made in USA**

## **Cadillac CTS**

### **Navigation Data Update Disc USA and Canada**

Version 2.00

**When handling the DVD disc, be careful of the following:**

- Handle the disc very carefully to avoid contamination or flaws.
- Signals may not read out properly if the disc gets contaminated or flawed.
- If the disc gets soiled, use a soft cloth to gently wipe it out from the center of the disc to the outside.
- Do not use any cleaners or solvents.
- Do not use the disc to rest on while writing or drawing using any writing utensil or attach a seal to any of the sides of the disc.
- Do not keep the disc in direct sunlight, high temperatures, or humidity.
- After using the disc, place it back into the original case.

# Navigation Data Update Disc

Version 2.00

Coverage: USA, Canada, Hawaii, Puerto Rico, Virgin Islands

Updated Data: Map DB, Navigation SW, Audio SW

Update Time: Generally, version update will take 3 hours.

## Warnings:

- **Please ventilate enough** when you update in a garage or indoors. You are at risk of CO intoxication.
- **Please do not disconnect battery** in update mode. The update would not be normalized, and it may cause system breakdown.
- **Please do not eject the disc** during update. The update would not be normalized, and it may cause system breakdown.
- **Please keep the engine on** while executing the update of Navigation Data. The battery may go flat if you update without charging the battery.
- Driving on a rough surface while updating may result in Navigation SW Update failure. Please avoid rough grounds and bumpy roads, and drive softly.

## Update procedure:

1. Turn ignition on and wait for the radio to wake up.
2. Press the “Power” button of the Navigation Radio to turn on the radio.<sup>1</sup>
3. Press the “Navi screen up/down” button to set the screen in full screen position.<sup>2</sup>
4. Insert update disc partway into the slot, label side up.
  - a) The disc will be pulled into the radio automatically.
  - b) After the disc is loaded, the update confirmation screen will be displayed on the screen.
5. Press the “Update” screen key.
6. Input the Authentication Code using the alphanumeric screen keys, then press the “Enter” screen key.<sup>3</sup>
  - a) If the correct code is entered, the system will update.
  - b) First, the radio resets itself automatically and starts Audio SW update.<sup>4</sup> While updating the Audio SW, the update progress screen is displayed. When the Audio SW update is completed, the system displays “Completed” message.<sup>5</sup>
  - c) After the Audio SW updates, the system resets automatically again and continues to the Navigation SW update.<sup>4</sup> While updating the Navigation SW, the update progress bar is displayed on the screen. When the Navigation SW update is completed, the system displays “Completed” message.<sup>6</sup>
  - d) After the Navigation SW updates, the system resets automatically again and continues to the Map DB update.<sup>4</sup> While updating the Map DB, the update progress bar is displayed on the screen. When the Map DB update is completed, the system displays “Completed” message.<sup>7</sup>
  - e) After the Map DB updates, the “System Reset” message is displayed and the system resets automatically.<sup>4</sup> After the radio wakes up, the update disc is ejected.
7. Please remove the disc from the radio.<sup>8</sup>
8. Navigation data update is complete.

## Notes:

<sup>1</sup> If the radio wakes up in “Power off” mode.

<sup>2</sup> If the radio wakes up in half screen.

<sup>3</sup> If you do not have a valid Authentication Code, please contact your local GM dealer.

<sup>4</sup> The behavior of the radio at the reset may vary according to the timing: the screen may just turn black or white, the display might move up and down, or the opening animation may be displayed.

<sup>5</sup> Update of the Audio SW will be completed in about 10 minutes.

<sup>6</sup> Update of the Navigation SW will be completed in about 10 minutes.

<sup>7</sup> Update of the Navigation data will be completed in about two and a half hours.

<sup>8</sup> If the disc is automatically reloaded before you remove it from the slot, please select the “Disc” tab in the audio screen. The disc is automatically ejected with a message.