

GRACENOTE MEDIA DATABASE UPDATE DVD Rev.981

For use with Cadillac CTS Navigation Radio
GM p/n: xxxxxxxx

Update procedure:

1. Turn ignition on, and wait for the radio to wake up.
2. Press 'power' button of Navigation Radio to turn on the radio. (*1)
3. Press 'Navi screen up/down' button to set the screen in full screen position. (*2)
4. Insert the update disc partway into the slot, label side up.
 - 1) The disc will be pulled into the radio automatically.
 - 2) After the disc is loaded, update Confirmation screen will be displayed on the screen.
5. Press "Update" screen key .
 - 1) System is displayed message of "Beginning update process. System reset..."
 - 2) After reset, CDDB update starts, automatically. (*3)
 - 3) When CDDB update is completed, system is displayed message of "completed".
 - 4) After message, system is displayed message of "System reset..." and the system resets automatically. After the radio wakes up, ejects the update disc. (*4)
6. Please remove the disc from the radio.
7. CDDB Update is completed.

Note*

- (*1) If the radio wake up in Power off mode.
(*2) If the radio wake up in half screen.
(*3) Update of CDDB will be completed in about 10 minutes.
(*4) If disc is automatically reloaded, please select "Disc" tab in the audio screen. After the disc is loaded, update Confirmation screen will be displayed on the screen. After it, press "Cancel" screen key. Disc is ejected.

This disc contains data collected approximately by Feb. 2008.

The data provided by the Gracenote media database offered from "Gracenote(R) music recognition service " may not be 100% accurate.

Warnings:

- Please ventilate enough when you update in a garage or indoors. You are at risk of CO intoxication.
- Please do not disconnect battery in update mode. The update would not be normalized, and it may cause system breakdown.
- Please do not eject the disc during update. The update would not be normalized, and it may cause system breakdown.
- Please keep the engine on while executing the update of CDDB. The battery may go flat if you update without charging the battery.
- Driving on a rough surface while updating may result in CDDB Update failure. Please avoid rough grounds and bumpy roads, and drive softly.

About Gracenote music recognition service : Music recognition technology and related data are provided by Gracenote(R).

Gracenote(R) is a registered trademark of Gracenote, Inc. The Gracenote logo and logotype, and the "Powered by Gracenote" logo are trademarks of Gracenote.

Unauthorized copying, hiring, reproduction, storage in a retrieval system, or transmission in any form or by any means, electronic, mechanical, or otherwise, prohibited.